

Removal of Inorganic Elements in Pine (mg/kg)

	Native	Water Wash	Acid Wash	EDTA Wash
Al	7.0	5.1	3.2	3.0
Ba	2.8	2.8	1.1	2.3
Ca	620	559	179	415
Cd	0.15	0.15	0.06	0.06
Co	0.02	0.02	0.01	0.01
K	431	183	101	148
Mg	174	157	54	133
Mn	61	55	19	23
Ni	0.18	0.17	0.09	0.08
P	51	16	21	21
V	0.02	0.02	0.01	0.01
Zn	6.6	6.3	2.4	2.6